

149.06:33-09:30 (148.14:23-06:33)	2h56m of realtime 1024bps data plus 16h10m of recorded 512bps data played back at 4kbps was lost due to DSS-34 High Electron Mobility Transistor (HEMT X/Ka band) problem. No command activity took place. DR C105048 refers.